MONSANTO

From:	Gordon A. Grundma	nn CS6G		Corporate Engineering	(4-6112)
Date:	September 7, 1984		cc:	L.C. Beck L.V. Bumbicka	CS6G 1740
Subj:	Project Progress Meeting		R.M. Calles E.R. Hartman	CS6G CS6G	
Re:	CEA 3808, Main So	uth Trunk	Sewer	P.R. Hoemann L.C. Kreh	1740
TO:	T.N. Carrico C.M. Crain R.C. Ferrario K.W. Lichtenheld R.L. Nelson O.N. Shipley T.W. Wright	1740* CS6G CS6G CS6G 1740 1740* CS6H		F.A. Mayse R.J. Murphy R.L. Wiese * Present at meeting	F2ED CS6G 1740 CS6G

Following are minutes of the Project Progress meeting held at the Krummrich plant on Thursday, September 6, at 10:00 a.m.

- 1. Craft labor contracts are still unresolved. This continues to hold up the start of the sewer construction work by Alberici.
- Installation of the temporary fire mains continues. One tie-in was made this week and two other tie-ins are planned for next week.
- 3. The Health and Safety procedure is in preparation by <u>D. Nelson</u> and <u>K. Storms</u>. This procedure covers the testing for contaminated soil as well as the safety procedures required for workers, etc., who are exposed.
- 4. D. Nelson advises that a storage area for contaminated soil has been selected. Final approval of this area is in progress.
- 5. Alberici furnished a preliminary construction schedule on 08/31/84 covering the first 450-foot of the sewer to manhole 1-EE. Review of this schedule is in progress.
- 6. The two railroad tracks east of ACL cannot be out of service for extended periods of time. As a result, temporary trestles will probably be built to allow continuation of rail traffic during the sewer construction work. (tracks 8E & 8F).

Current plans indicate that ACL will be shut down for a couple of weeks in late November. The temporary trestles need to be installed at this time. Preparations for design work and material purchases need to be started now to meet this timing. Lichtenheld and Nelson.

The railroad track east of BBW (track 8C) also needs to be reviewed to see if rail loading can be accomplished from the north during construction. D. Nelson.

WGK 4084875

T.N. Carrico, et al September 7, 1984 Page 2

Limited access requirements to the south end of the BBZ storeroom during construction need to be reviewed. Nelson

7. The tie-in point for the yard drain on drawing C6 near manhole 2-EE needs to be reviewed. Nelson and Lichtenheld.

Weekly meetings will continue to be held at the construction trailer at 10:00 a.m. on Thursday mornings.

Gordon Grundmann

mb

1021z

WGK 4084876